No. 378/FSR/CFO/MZ/2021-22

Office of the
Chief Fire Officer
Karnataka Fire and Emergency Services
Mysuru Zone, Mysuru-570 016
Date: 09-03-2022

To,
The Secretary
Mysore Diocesan Educational Society
St. Joseph's Complex
Jayalakshmipuram
Mysuru.

Sub: Issue of 'Fire safety recommendation' to existing "St. Joseph's Central School" building at Yelwala, Mysuru.

Ref: Your request dated: 01-02-2022.

With reference to the subject above cited, the premises of "St. Joseph's Central School" building at Yelwala, Mysuru was inspected by me on 08-02-2022 with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and details as under.

## **ANNEXURE-1**

## **Group B Educational Buildings**

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub Division B1 & B2

(These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory.)

Part-A. Details of the building / premises :-

01	Name and Address of the	:	The Secretary
	Applicant.	100	Mysore Diocesan Educational Society
			St. Joseph's Complex
			Jayalakshmipuram
			Mysuru
02	Name and Address of the premises.	:	St. Joseph's Central School
			Yelwala, Mysuru
03	Name and address of the	:	The Secretary
	Building owner	1300	Mysore Diocesan Educational Society
		1	St. Joseph's Complex
			Jayalakshmipuram
			Mysuru EFFIRE OF
04	Number of buildings	1	01 School building.
er II	SEPH'S CENTRAL SCHOOL		570016

ST. JOSEPH'S CENTRAL SCHOOL
Mysure-Hunsur Head, Yeleval Post
Mysure Dist - 577 130

Si Joseph's Cevir: I School

MYSURUZONE 570016

00	Number of floors				
06	Floor-wise details of occupancy:-	:	Ground + 02 Upper floors.		
07	Height of the building	:	Ground floor:- 15 Class rooms, Principal room, Staff room, Library, Sports room, Store room & Office room.  First floor:- 17 Class rooms, Staff room, Computer lab, Store room & Office room.  Second floor:- 17 Class rooms, Staff room, Library, Store room & Office room.		
08	Site area	:	11.40 mtrs.		
		:	41900.18 Sq.mtrs.		
09.	Built-up area of each floor:-				
		:	Ground floor:- 1803.38 Sq.mtrs. First floor:- 1728.89 Sq.mtrs.		
10.	Total built-up area		Second floor:- 1728.89 Sq.mtrs.		
11.		:	5261.16 Sq.Mtrs.		
11.	Surrounding properties:-				
	North (front)	:	Mysore-Hunsur road.		
	South (rear)	:	12.00 mtrs. wide road.		
	East (side)		Open ground.		
	West (side)	:	Open ground.		
12.	Set-back area available around the building:-				
	North (front)	:	Min. 30.00 mtrs.		
	South (rear)	:	Min. 15.00 mtrs.		
	East (side)	:	Open ground.		
	West (side)	:	Open ground.		

Part-B. On inspection of this School premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety

Sl. No. (1)	Details (02)	Existing (03)	Recommendations (04)
1.	Accessibility	The premises is accessible from 24.00 mtrs, wide Mysore to Hunsur main road on Northern side. This road is hardened to carry weight of 55.000kgs.	8.
	ST. JOSEPH'S CENTRA  ST. JOSEPH'S CENTRA  Mysore Hunsur Read, Yel  Mysore Dist - 577	St. Joseph's Ce	At Yelwal Me Scanned hy Cam Scanne

12.	Number of	02 Entrances eac	3	在1000000000000000000000000000000000000
	entrances	mtrs	h of 06.00	
2	Number of	provided.	nas been	Adequate.
3.		Number of the 03 nos.		
	staircases available	staircases	vo nos.	
		Width of	01.50	
		staircases	mtrs.	
		Width of treads	30 cms.	
		Height of risers	15 cms.	
		No. of risers per	12 nos.	Complied.
	The second second	flight	7.00	
		Height of	1.00 mtrs.	
		handrails		
		Head room	02.50	
		clearance	mtrs.	
	Diesel generator	Not provided.		Diesel generator of 15 KVA
	THE RESERVE TO BE SEEN TO SEE SEE			capacity should be provided
	STATE OF BRIDE	A PERSONAL PROPERTY OF THE PERSON NAMED IN COLUMN TO PERSON NAMED IN C		to supply alternative power
	Portable Fire	Th.		supply.
		Not provided		A. One Water mist
	extinguishers			extinguisher of 9 liters
				capacity should be kept near
				each staircase landing.
	and the Families and	Park Town		B. One Mechanical foam
	Single market when the			
				extinguisher of 9 liters capacity & One ABC type
				extinguisher of 6Kgs
				capacity should be provided
No.				near Diesel Generator.
	STATISTICS OF STATISTICS			C. One CO2 Type fire
	FR IN SERVICE BY			extinguisher of 4.5 Kgs
				capacity should be provided
				near each electrical board &
	MAN THE PROPERTY.			electrical room.
100	BOOK STREET			D. One ABC typ
	Charles and the state of the st			extinguisher of 6kgs capacit
1	Charles and the same of the sa			should be located as to l
				available within 15.00mt
	0.			radius.
-1-	C/ AM			A LIKE

ST. JOSEPH'S CENTRAL SCHOOL

Mysore-Hunsur Road, Veleval Post

Mysore Dist - 577 130

St. Joseph's Central School

Avsore Hunsur Road, folivial Access

175URU ZONE 570016

	1 4.	cust and hose reel		
		hose	Not provided.	
				Hose
				Hose reel hose near the
				Une hose real 1-
				TOP PARTY 1000
				sq.mtrs) shall be provided.
-				The hose and he provided.
1				The hose reel hose min 19
				size and 100
				Internal diameter made c
				G.I 'C' class pipe and of
1				adequate length
				adequate length to reach the
1				farthest point of each floor
1				should be provided with chart
1		STATE OF THE PARTY		on branch having a nozzlo c
1				5mm size. The hose reel hose
1				should be connected at each
1	7.	m		landing of
-		Terrace tank over	Not	landing of each building/
1	-13/31	respective tower	Not provided.	block wing/ tower.
1		terrace		Each system should be
1		terrace		connected to an over hand
1				tank of 5,000 ltrs capacian
ı	-	PERSON WILLIAM		and further if basement is
1	1833	ACTION OF SHIP SHIP SHIP SHIP SHIP SHIP SHIP SHIP		provided the tank capacity
1	1			shall be increased to 10,000
1				ltrs capacity.
-				ters capacity.
1				/mi
			The second of th	(The water tank should be
1				kept exclusively for
	1000			firefighting purpose)
1				
				Note: If the existing building
	000			is not capable of sustaining
				the weight of account
		AND THE PROPERTY.	SANGER CONTRACTOR OF THE PARTY	the weight of 5,000/10,000
		THE PERSON NAMED IN	Charles The Late of the Late o	ltrs. tank capacity provision
			Salar and Control of the Control of	shall be made to provide
				water tank on the side of the
	12 12	TOTAL COLUMN		building with support from
	100			ground level by providing
				RCC column structure or MS
			PROPERTY AND ADDRESS OF THE PARTY OF	golumn at
	100	Frank Carlotte		column structure.
	MAN TO			
	133		0	If there is no option to
	7 1 2	STATE OF THE PARTY OF	XS	provide even the above
		11.	11/1	mentioned overhead tank
		and and	N choo	provision shall be made to
		STORIGHAM SCHOOL SCHOOL	"Look stella walls invisor	provide underground water
		WE CENTRALINATION	1 Sec Centralival	
	1	OSEPH'S CENTRAL SEPASION OSEPH'S CENTRAL Velwal Pasion OSEPH'S CENTRAL Velwal Pasion Osephanosure Dist. 571 130	John Hang.	tank of capacity TRUD
	51.3	Mysore Mysore	Ct. Jos Hunsun	submersible pump 98 HP
		OSEPH'S CENTRAL SCHOOL OSEPH'S CENTRAD TO 130 MYSO'S HUNSU'S DIST. 577 130	St. Josephisur Hurd Vellwal Mysora	capacity.
			William Control of the Control of th	A45000 5 /
				图 5/000000000000000000000000000000000000

h	At the terrace tank	No.	
70.	level with minimum pressure of 3.5 kg/cm <sup>2</sup>	Not provided.	Each system should be connected to an booster pump of 450 LPM or of 5 HP capacity.  (Further the system should be connected to an alternative source of power supply)
).	Escape routes	Not provided.	Directions in which the students have to move in the event of any emergency should be displayed in the corridor on each floor during
10.	Fire order (Fire Safety plans)	Not provided.	A notice board have been indicated the action should be taken by the employees in case of any emergency should be displayed with the telephone number of Hebbal Fire Station i.e. 0821-2512101 & 101 and the nearest Ambulance service and Police Station.
11.	No smoking board.	Not displayed.	COTPA Sec-4, direction NO Smoking area smoking here is an offence board should be written in English & Kannada both language shall be prominently displayed at inside the entry / exit of the each floor.  A Fire Siren shall be installed
12.	Fire Siren	Not installed	in the premises to inform the inmates in case of fire emergency and evacuate the area.  A Fire Nodal Officer shall be
13.	Nominate one Fire Nodal Officer		nominate either from teaching or non teaching staff.

ST. JOSEPH'S CENTRAL SCHOOL

Mysore-Hunsur Road, Yelwal Post

Mysore Dist - 577 130

St. Joseph Gentral School St. Joseph Good. Tellwal. Mysore Hunsur Joad. Tellwal. Mysore

- A) Explosive and flammable materials should not be stores in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.
  - B) Accumulation of combustible waste in and the premises should be avoided.
  - C) The exit ways shall be always kept clear without any obstruction.
  - D) Liquefied petroleum gas should not be stores in the building.
  - E) The doors shall not be kept locked / latched during working hours and shall be free from obstruction.
  - F) During the class hours the class room doors shall not be locked from inside to outside.
  - G) As per Honorable Supreme Court order all teachers and staffs shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14th of every year be conducting Fire Safety drills with co-ordinate Fire Service department.

Under the above circumstance, the Karnataka Fire & Emergency Services Department is issuing Fire Safety Recommendation of "St. Joseph's Central School" building at Yelwala, Mysuru subject to condition and compliance of the above recommendations in Column-4 of serial-B within 3 months and compliance to the undersigned.

"This Fire Safety Recommendation is valid for Only One Year from the date of issued and it is renewable".

All requirements recommended above are as per National Building Code-2016 Part-4 clause 3.1.3 of Fire and Life safety will have to be complied with mandatorily.

Yours faithfully

200 (a)3/2022 Karnataka Fire & Emergency Services Mysuru Zone, Hebbala Fire Station MYSURU-570016

St. Joseph's Central School A France Annall Have A Have A HAVEOUR